Date:

Monday, 29/09/2008 11:54:58 AM

User:

Julie Lecocq

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

S.O. No. :

Job Number **Estimate Number**

: 42319 : 10791

P.O. Number

This Issue

: 29/09/2008

: NC Prsht Rev.

First Issue : //

Previous Run

Written By

Comment

: 42314

Checked & Approved By

: Est Rev:B 05.09.23

: SKIDTUBES Type

Drawing Name

Part Number Drawing Number

: D3282041 : D3282 REV C

: FLOAT WEB

Project Number Drawing Revision

: N/A : C

Material

: 10/10/2008 **Due Date**

Qty:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

D2792130

Procedure change KJ/JLM

EXTRUSION

5.0000 Each(s)

Comment: Qty.:

Pick:

1.0000 Each(s)/Unit Total:

Qty Part Number 1 D2792-130

Description Batch Extrusion 33518

Identify as D3282-1

2T 08-10-01

2.0

SKIDTUBES 1

SKIDTUBESS RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Cut to length as per Dwg D3282.

2- inspect for surface damage as per QSI0018

10.01-30

3.0

HAAS1

HAAS CNC VERTICAL MACHINING #1







Comment: HAAS CNC VERTICAL MACHINING #1

1-Machine as per Folio FA579 & Dwg D3282

2-Deburr

4.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	SES					
DATE	STEP	PRO	CEDURE CHA	NGE		Ву	Date	Qty	Date: Date:	Approval QC Inspector
	ļ			<u>.</u>						
Part No	:	PAR #:	Fault Cate	gory:	NCR	: Yes N	lo DQ	A:	Date: _	,
	R	esolution:	Dispositio	n:	QA:	N/C Clo	sed:		Date:	
NCR:		V	VORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC			tion B		Verific	cation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date		on C	Chief Eng	QC Inspector
							}		į	
									ļ	

NOTE: Date & initial all entries

Monday, 29/09/2008 11:54:58 AM Date: User: Julie Lecocq Process Sheet Drawing Name: FLOAT WEB Customer: CU-DAR001 Dart Helicopters Services Job Number: 42319 Part Number: D3282041 Job Number: Seq. #: **Machine Or Operation: Description:** SECOND CHECK 5.0 QC8 18/10/01 Comment: SECOND CHECK HAND FINISHING RESOURCE #1 HAND FINISHING1 8-10-3 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 INSPECT POWDER COAT/CHEMICAL CONVERSION QC3 7.0 POWDER COAT/CHEMICAL CONVERSION D32831 Doubler 8.0 10.0000 Each(s) Comment: Qty.: 2.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description Batch 2 D3283-1 Doubler Rivet, Universal Head 9.0 MS20470AD47 Comment: Qty.; 57.0000 Each(s)/Unit Total: 285.0000 Each(s) Pick: **Qty Part Number** Description N 7-10-6 57 MS20470AD4-7 Rivet SKIDTUBESS RESOURCE 1 SKIDTUBES 1 10.0 Comment: LANDING GEAR RESOURCE 1 1-Install doublers as per Dwg D3282. Apply LPS-3 between doublers and web A/RN/ALPS-3 12 10 3 16 7 4 INSPECT WORK TO CURRENT STEP 11.0 QC5 Comment: INSPECT WORK TO CURRENT STEP

Dart Aerospace Ltd

W/O:			V	/OR	K ORDER CHANGE	ES					
DATE	STEP	PRO	OCEDURE CH	IANG	E		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Ca	tegor	y:	NCR	Yes N	lo DQ .	A:	Date: _	
	Re	esolution:	Disposit	ion: _		QA:	V/C Clo	sed:		Date: _	
NCR:			WORK OR	DER	NON-CONFORMA	NCE	(NCR))		·-	
DATE	STEP	Description of NC			rrective Action Section		01 0	Verific	cation	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	1	Action Description Chief Eng		Sign & Date	Sect	ion C	Chief Eng	QC Inspector
									·		
								•			

NOTE: Date & initial all entries

Date: User:

Monday, 29/09/2008 11:54:58 AM

Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT WEB

Job Number: 42319

Part Number: D3282041

Job Number:



Seq. #:

Machine Or Operation:

Description:

12.0

PACKAGING 1

PACKAGING RESOURCE #1





Comment: PACKAGING RESOURCE #1

Identify and Stock Location:



8-12-6

13.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL TION/W/O RELEASE

Job Completion



N & 20-07

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	BES					
DATE	STEP	PRO	OCEDURE CHA	ANGE	E	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				·						
Part No	,	PAR #:	Fault Cate	egory:	_ NCR:	Yes N	lo DQ	A :	Date:	
	R	esolution:	Disposition	on:	QA: N	/C Clo	sed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCR)			,	
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sec Action Description Chief Eng		ign & Date	Verific Secti		Approval Chief Eng	Approval QC Inspector
								,		

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order: 42	7/10
Description: Float Web	Part Number: D32	82-041
Inspection Dwg: D3282 Rev: C	Pag	e 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

Х	First Article	Prototype	ė
	I HSLAILICIE		


Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
126.6	+/-0.100	126.6	/			
1.500	+/-0.010	1.500	1			
3.000	+/-0.010	3.000	1			
6.000	+/-0.010	6.000	/			
1.250	+/-0.010	1.250	/			
30.000	+/-0.010	30,00	/			
1.500	+/-0.010	1,500	_			
72.01	+/-0.030	72-01	~			
61.75	+/-0.030	61.7(-	7			
57.50	+/-0.030	57.<	7			
49.19	+/-0.030	49.19	7			
43.94	+/-0.030	43.94	1	·		
39.69	+/-0.030	37,69				
26.68	+/-0.030	26.63	1			
0.55	+/-0.030	.540	/			
1.970	+/-0.010	1.970	1			
2.38	+/-0.030	2.380	~			
0.05	+/-0.030	-045				
	·					


Measured by:	Audited by:	Prototype Approval:	N/A
Date: 08/10/01	Date: 0% 16/61	Date:	N/A

Rev	Date	Ćhange	Revised by	Approved
Α	07.04.02	New Issue	KJ/JLM	
			101	Trong -









Copyright © 2004 by DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.